

# Oil Field Environmental Incident Summary

**Incident:** 20150516183745      **Date/Time of Notice:** 05/16/2015 18:37  
**Responsible Party:** FIDELITY EXPLORATION & PRODUCTION COMPANY  
**Well Operator:** FIDELITY EXPLORATION & PRODUCTION COMPANY  
**Well Name:** SCHMIDT 11-2H  
**Field Name:** DUTCH HENRY BUTTE      **Well File #:** 23396  
**Date Incident:** 5/16/2015      **Time Incident:** 08:00      **Facility ID Number:**  
**County:** STARK      **Twp:** 140      **Rng:** 97      **Sec:** 11      **Qtr:**  
**Location Description:**

**Submitted By:** Edward Pottorff      **Received By:**  
**Contact Person:** Edward Pottorff  
1801 CALIFORNIA STREET  
SUITE 2500  
DENVER, CO 80202

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	30	Barrels	27	Barrels	30	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 5/28/2015      **Clean Up Concluded:** 5/18/2015

**Risk Evaluation:**

There were no immediate risks identified.

**Areal Extent:**

**Potential Environmental Impacts:**

Only the gravel within the lined containment berm was affected.

**Action Taken or Planned:**

Upon discovery of the spill, the recycling pipeline was valved off and the Fidelity Operations Supervisor was notified. A VAC truck was then mobilized to the well/facility site and began collecting the spilled oil and putting it into the facility production tanks. Additional cleanup will consist of cleaning the affected gravel within the containment berm. Also, the pipeline fitting will be repaired before it is put back into service.

**Wastes Disposal Location:****Agencies Involved:****Updates**

---

**Date:** 5/18/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

According to the incident summary, this spill remained on location within the dikes. NDIC retains oversight.